


VOLTAGE REGULATOR

VR600 - VOLTAGE REGULATOR - MERCURY

1995-2005 (25-40HP - 2 Cyl.); 1987-2007 (45-90HP - 3 Cyl.); 1989-2006 (90-125HP - 4 Cyl.); 1992-2000 (150-225HP - 6 Cyl.)

Yamaha 65W-81960-00-00; Yamaha 65W-81960-10-00; Mercury 815279; Mercury 815279 1; Mercury 815279 2; Mercury 815279 3; Mercury 815279 4; Mercury 815279 5; Mercury 815279-1; Mercury 815279-2; Mercury 815279-3; Mercury 815279-4; Mercury 815279-5; Mercury 815279A 1; Mercury 815279A 2; Mercury 815279A 3; Mercury 815279A 4; Mercury 815279T; Mercury 815279T 2; Mercury 815279T 3; Mercury 815279T 4; Mercury 815279T 5; Mercury 817411; Mercury 817411 1; Mercury 817411-1; Mercury 830179; Mercury 830179 2; Mercury 830179-2; Mercury 830179A 1; Mercury 830179A 2; Mercury 830179A 3; Mercury 830179T; Mercury 854514; Mercury 854514 1; Mercury 854514A 1; Mercury 854514T; Mercury 854514T 1; Mercury 854515; Mercury 854515 1; Mercury 854515-1; Mercury 854515A 1; Mercury 854515T 1; Mercury 856747T 1; Mercury 856748; Mercury 883072; Mercury 883072T



TILT TRIM SENDER

TS001 - TILT TRIM SENDER - MERCURY

Mercuriser Stern Drives: MC-I, R, MR, Alpha, Alpha Gen II, Bravo drives

Sierra 18-7633; Mercury 805320A03; Mercuriser 17693A2; Mercuriser 63115A12; Mercuriser 805320A1; Mercuriser 88678A4; Mercuriser 88678A5; Mercuriser 96863A15



IMPELLER KITS

WP001 - IMPELLER & HOUSING - MERCURY

2000 & newer MCM V-6 & V-8 (305, 350 & 496 CID) engines w/ brass sea water pump

Sierra 18-3160-1; Mercuriser 46-862914A13; Mercuriser 8M0118062; Mercuriser 8M0139984; EMP 46-46301



WP002 - IMPELLER/HOUSING - VOLVO PENTA

Indmar 302 Ford Engines; Crank shaft mounted; DO NOT USE ON LT-1 or LTR engines

Sierra 18-3586-1; Indmar 665011; Pleasurecraft RA057023; Volvo Penta 841640; Volvo Penta 857451



WP003 - IMPELLER/HOUSING - VOLVO PENTA

Indmar 351 Ford Engines; Most GM Engines with 1 1/4" Hose Outlet; DO NOT USE ON LT-1 or LTR engines

Sierra 18-3587-1; Indmar 685001; Johnson Pump 10-24232-1;




WP004 - IMPELLER/HOUSING - MERCURISER

Mercuriser V-8 Engines with V-belt and 2-piece pump

Sierra 18-3600; Mercury 46-72774A32; GLM 12093; Mercuriser 46-72774A32; Mercuriser 46-72774A11; Mercuriser 46-73823A7; Mercuriser 46-63450A2; Mercuriser 46-59112A2



NEW PRODUCTS 2022-2023



ARCOMARINE.COM

3921 W. Navy Blvd. Pensacola, FL 32507
1.800.722.2720 | arco@arcomarine.com

ROTATING ELECTRIC

6226 - TILT TRIM SYSTEM - VOLVO PENTA

Volvo Penta SX Late model w/ coarse thread
OMC Stern Drive: 1991- 1998

OMC Stern Drive; 3855744; 3855745; 3857489; 3858069; 3860879; 986914
Volvo Penta 3587079; 3854030; 3855745; 3857489; 3860879

Sierra 18-6804



3439 - OUTBOARD STARTER - SUZUKI

Johnson Outboard 2003 - 2006 90HP - 140HP; Suzuki Outboard 2001 - 2009 90HP; 2009 - 2014 100HP; 2001 - 2014 115HP; 2002 - 2014 140HP

Suzuki 31100-90J01; Sierra 18-6831; Protorque PH130-0071



5415 - OUTBOARD STARTER - MERCURY

Mercury 80HP - 115HP 4-stroke outboard engines;
Mercury 2009-2010 80HP Jet Optimax engines

Mercury 879345T77; Mercury 8M0038387

ARCO is first to aftermarket



IGNITION COMPONENTS

IG001 - IGNITION SENSOR - MERCURUISER

GM V-6 & V-8 Engines w/Thunderbolt IV & V Ignition; 350MAG MPI; 4.3L Mercruiser; 5.0L Mercruiser; 1981 - 1997 5.7L Mercruiser engines with THUNDERBOLT electronic ignition

Sierra 18-5116-1; CDI Electronics E11-0005; EMP 87-08107; GLM 73110; Mercury 87-892150Q02



IG002 - IGNITION COIL- MERCURY

Mercury 1970-2006 (6-40HP - 2 Cyl.); Mercury 1976-1997 (45-90HP - 3 Cyl.)
Mercury 1976-1997 (45-125HP - 4 Cyl.); Mercury 1976-2000 (90-225HP - 6 Cyl.)

Sierra 18-5186; CDI Electronics 184-0001; Force 339-7370A23; Mercury Marine 339-832757A4



IG003 - IGNITION COIL- JOHNSON/EVINRUDE

1972 - 2006 Johnson Evinrude Outboard Engines

Sierra 18-5176; CDI Electronics 183-2366; EMP 300-00730; GLM 72080; Johnson Evinrude 0584561



IG004 - IGNITION COIL- JOHNSON/EVINRUDE

1985-2006 (2.5-55HP - 2 Cyl.; 1995 (50HP - 3 Cyl.)
1995-2006 (80-115HP - 4 Cyl.); 1991-2006 (105-175HP - 6 Cyl.)

Sierra 18-5170; CDI Electronics 183-3740; EMP 300-05837; Johnson Evinrude 583298;
Johnson Evinrude 583740; Mercury 300-05837; Mercury Marine 879614



IG005 - IGNITION COIL- MERCURY

Mercury 2004 - 2018; 75HP - 400HP

Sierra 18-5154; CDI Electronics 184-0002; Mercury 339-880615T01; Mercury 339-8M0039809;
Mercury 339-8M6002327; Mercury 880615T01; Mercury 8M0039809; Mercury 8M6002327



CS001 - CONTACT SET- MERCURUISER

Mercruiser 34235; Mercruiser 34235T; Mercruiser 35637;
OMC Stern Drive 380538; Chris-Craft 16.69-00049

Sierra 18-5311; CDI Electronics E66-0017



» ALL NEW ARCO PARTS

We're expanding our product offering to include quality engine service parts! Contact your ARCO distributor or sales associate for more information.

IG006 - IGNITION COIL- MERCURY

Mercruiser 496 MAG; Mercruiser 8.1L HO; Volvo Penta 8.1L; Volvo Penta 8.1GI; Volvo Penta 8.1GSI; Volvo Penta 8.1GXI

Sierra 18-7648; CDI Electronics E18-0006; Volvo Penta 3861267; Mercruiser 392-881732
Pleasurecraft R117012



IG007 - IGNITION COIL- OMC

1993 - 1996 5.0 Volvo Penta; 1993 - 1996 5.8 Volvo Penta; 1993 - 1996 OMC Stern Drive

Sierra 18-7492; CDI Electronics E18-0010; OMC 3854161; OMC 987680; Volvo Penta 3854161



IG008 - IGNITION COIL- MERCURY

Sierra 18-5442; EMP 300-03755; Mercruiser 350 - 8.1L Stern Drive Engines

Fits GM V-8 engines with Delco; HEI ignitions (except MPI engines with ECM 555); 1994 - 1996 350 MAG V-8; 1994 - 1996 5.7L; 1997 350 MAG ALPHA; 1997 5.7LX BRAVO; 1998 5.7L EFI



IG009 - IGNITION COIL- HONDA

Honda 2004 - 2007 135HP - 150HP Outboard Engines

Sierra 18-7494; CDI Electronics 180-0001; Honda 30520-PNA-007; Honda 30520-RRA-007



IMPELLERS

IP001 - IMPELLER - MERCURY

MCM 4.5L MPI; 2000 & newer MCM V-6 & V-8 (305, 350 & 496) engines w/ brass sea water pump

Sierra 18-3016-1; Mercury 47-8M0104229; Mercury 47-862232A2



IP002 - IMPELLER - VOLVO PENTA

Volvo Penta; OMC

OMC 3858256; Volvo Penta 21951346; Volvo Penta 3862281; Volvo Penta 3850107; Volvo; Penta 87740; Volvo Penta 875811; Volvo Penta 876243; Sierra 18-3081; Jabsco 1210-0001-P



IP003 - IMPELLER - JOHNSON/EVINRUDE

Johnson Pump

Johnson Pump 09-45825; Sierra 18-3089



IP004 - IMPELLER - MERCURY

Mercruiser Stern Drives

Mercruiser 46-72774A89; Sierra 18-3155

